

Parliament of Sint Maarten

Staten van Sint Maarten

To the Hon. Minister of Education, Culture, Youth and Sports Mr. W.S. Smith

Philipsburg

UV/369/2018-2019

Philipsburg, July 17, 2019

Re: Questions from MP R. Brison concerning monument status of historical buildings on Front street

Hon. Minister Smith,

Herewith I submit to you questions posed by Member of Parliament, Mr. R. Brison pursuant to article 62 of the Constitution and article 69 of the Rules of Order of the Parliament of Sint Maarten.

The letter is self-explanatory.

Yours truly

C.A.H. Reterson

Vice President of Parliament



Rolando Brison

Member of Parliament

Chairlady of Parliament Sarah Wescott-Williams % Mrs. Nancy Joubert, Secretary General of The Parliament of St. Maarten STATEN VAN SINT MAARTEN
Ingek. | 1 JUL 2019
Volgnr. | 5/12/01/8-6
Par. | 6/8

Philipsburg July 3rd 2019

Re: Monument status of historical buildings on front street Good Day Madame Chairlady,

Through you, I would like to pose the following concerns and questions to the Minister of Education, Culture, Youth and Sports.

I have grave concerns of the status of many historical buildings in Philipsburg. Town is not just the center of our cruise tourism product, but also of immense historical and cultural significance to our people. Since the Minister has been to parliament for the appointment of members of the monument council, we have not heard back from the Minister on this body's plans for ensuring Philipsburg historical icons are preserved and designated as monuments.

This is particularly concerning, considering that the parliament has already approved since September 26th 2018 the members of the monument council. During this meeting, the Ministers assured parliament that "this will allow for the council to be extremely active in ensuring that all of our national monuments received the necessary urgent attention". The reports I have received however are much to the contrary, where many of our monument holders in St. Maarten are frustrated by the Ministry's and the Council's lack of effort in addressing various issues they face such as repairs, building permits, funding and information.

With that in mind, I am hereby requesting the following information:

The Parliament approved the monument council members on September 26th 2018. However I have learned that the members were only installed recently in March. Can the Minister please explain why he would allow such a major delay to occur, and not respect the wishes of parliament who approved these members to be installed? Does the Minister understand the implications of his lack of urgency having affected the ability of many monuments in St. Maarten to undergo urgent repairs and preparation for the hurricane season?

Does the monument council have the correct number of members on board, and sufficient expertise?

How many "urgent" requests versus how many "regular" requests for advice were sent to the Monument Council? Is the Minister allowing sufficient time for the Monument Council to conduct their proper due diligence in advising on reconstruction efforts of Monuments?

Can the Minister request an update from the Monument council to be shared with parliament on their current workload and backlog, and their plan for addressing these?

Does the Monument Council have any sort of budget for assisting monuments? How many requests and from which monument holders did the council receive requests for funding assistance? Did the Minister request from the trust fund any funding for the Monument council, if yes, how much, if not, why not?

Wilhelminastraat # 1, Philipsburg, Sint Maarten
Tel: + (1-721) 542-0812 / 542-0635 | Fax: + (1-721) 542-0306
Email: info@sxmparliament.org | www.sxmparliament.org

Attached to this letter are pictures of 3 monuments that the undersigned MP considers to be in particularly unacceptable state. These photo's are as follows:

- 1. The cistern before walter plants square
- 2. The property Watkins house Frontstreet #113
- 3. Frontstreet property "The Old House" Meetingbrief 363-1997

What is the status of the Monument Passangrahan? Why is the property being split up?

Can the Minister share with us why these properties have not been repaired as yet? What communication has he had with these property owners? What policies are in place?

Can we get a complete list of monuments, divided by districts?

Why has the monumental council not replied to owners of the properties of Frontstreet #113 as well as Property Meetbrief 363-1997 in regards to their urgent requests to begin repairs to the property?

What is the plan to ensure that the properties will be restored?

These are local families that want to rebuild, is the Ministry targeting local families and making it hard for them to rebuild, while foreign entities are being allowed to fast track their way to rebuilding efforts in St. Maarten?

We are counting on receiving on update in writing as soon as possible. The only other recourse then would be to call the Minister to parliament to answer to the members and give assurance that these things are being handled.

Kind Regards,

MP Rolando Brison

Minister of Culture
Government Building
Soualiga Blvd., Pond Island
St. Maarten





November 11th, 2017

Ref: Request for assistance & monument permit

Dear Honorable Minister;

I am addressing this letter to you on behalf of the Watkins/Apon families, who are the heirs and caretaker families of the Watkins Family home, situated on the 113 Front Street, Philipsburg.

The Watkins Family home is one of the few remaining national treasures on Front Street and with the passing of Hurricanes Irma and Maria, sadly enough it was partially damaged.

The roof was badly damaged, causing flooding to the main (original) structure of the building, thus causing mold. She would need repairs to the roof, and to the front porch, fumigation and treatment for mold and termites, and other repairs deemed necessary. Sadly, this monument was not ensured. Something we would like to discuss at a later date, as its very difficult to get insurance for such old homes and maybe with your influence, we, monument owners/care takers, would be able to get in the future.

It is in lieu of this we are respectfully requesting your assistance with the repairs and restoration of this **historical monument**, as well as the necessary monument permit, so that this "grand dame" can continue to shine and reflect the resilience of the St. Maarten people.

Respectfully,

Solange Apon

HISTORIC PROPERTY DAMAGE REPORT

Print out this form and fill in by hand to mail in. You may also email the information to daphne.thomas@sintmaartengov.org and sharine.allambey-duncan@sintmaartengov.org

Date, type, and name of event (i.e., flood, Hurricane Irma, etc.) Hurricane Trana Sept 6 ¹¹ , 2017
Name of Property: Warking Family Home
Address: 113 Front Ste. /District: Philipsburg
Your Name: APON Solange / Warking Anthony
Your Address (if different from above): Steel
Telephone: 580 - 1909 / 554 - 5110
Email: deur waarder. Opon @ gmail. com
Are you the owner of the property?no. If you are not the owner, please describe your relationship to the property and its owner (Please provide a signed power of attorney from the owner):
What kind of damage did the building(s) sustain? 3. Wdews / door 2. Front Poech
Will all of your damage be covered by your insurance?
If not, approximately how much money do you estimate that you will have to spend out-of-pocket to repair the damage?
= 90 K - 100K ANG
Can the Department of Culture be of some assistance to you in assessing damage and advising you on restoration and repairs? If so, please explain:
Please deliver this form to the New Government Building; in the name of: Daphne Thomas or by email to daphne.thomas@sintmaartengov.org and sharine.allambey-duncan@sintmaartengov.org .

Monument Permit Request Application Form Guidelines (Please fill out this form completely and accurately)

	I. General Information								
a) b)	Company name:								
c)	Type of entity: □ N.V. □ B.V. □ Ltd. □ Foundation □ Other, please specify. Local address:								
d)	Crib Number:								
e)	Telephone/Cel: 554/5110 580-1909								
f)	E-mail address: Solar A A Company Company Company								
g)	Is the contact person the same as above: No, if not fill out letter h.								
	Yes, continue to part II.								
	Other contact info:(PRINT NAME)								
i)	Telephone/ Cel: See E-mail address:								
	II. Permit Information								
a)	What is the request for?								
ы	□ Research Restoration □ Relocation □ Alteration □ Removal □ Conservation								
0)	h) Has a previous monument permit been requested for this parcel of land?								
c)	What is the administrative number of the previous Permit: MP#								
	Was the previous request □ Issued □ Denied □ Cancelled								
	III. Cadastral Information								
(a)	Location of parcel of land: Street Name: Front sheet 113 (Prev 95) District: Philipsburg								
(b)	What is the certificate of Admeasurement number?:/(no./yyyy)								
(c)	The applicant has this parcel of land in Ownership Long Lease Rent								
(d)	What are the square meters of the parcel of land?:								
(e)	Is there a subdivision plan for this parcel of land?: Yes No								
(1)	Is the property a registered monument? ■ Yes □ No								
	IV. Design and Cost								
(a)	What will be the usage of the monument? Residential: (Select one) Dwelling Apartments Guesthouse Hotel/Condo Commercial								
	□ Public Function								
	□ Other, please specify								
	The monument will be restored with:								
	□ Concrete blocks □ Reinforced Concrete □ Wood □ Steel								
	□ Other, please specify:								











4 +>

PREAM Architects

project:

Frontstreet 113 Apon

devision:

monument part

tel:

+1 721 522 8387

email:

All the arms of a

date:

2018-01-18

printdate:

2018-02-04

euro:

1.24790 USD

cur. :

hour wages:

17.50 USD

code	description CLEANING AND DEMOLITION	amountunit	mh/unit	mat/unit n	nanhours	manhours \$	material \$	subtotal \$	pera unit	remarks
11.00.20.10	demolition concrete demolition concrete roof slab	46.80 m2	2.00	35.00	93.60	4 620 00	4 000 00	0.070.00		
	total: demolition concrete	40.50 1112	2.00	35,00	93.60	1,638.00 1,638.00	1,638.00 1.638.00	3,276.00 3,276.00		
					00.00	1,000.00	1,000100	0,270,00		
11.00.30.10	demolition doors and windows									
	demolition doors and windows	1.00 pc	32.00	50.00	32.00	560.00	50.00	610.00	•	
	total: demolition doors and windows				32.00	560.00	50.00	610.00		
11.00.33.10	demolition roofing									
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	remove steel roof sheels battens tarp	79.92 m2	0.50	5.00	39.96	699.30	399.60	1,098.90	٠., ,	main roof
	remove steel roof sheels battens tarp	22.39 m2	0.50	5.00	11.19	195.91	111.95	307.86		porch roof
	total: demolition roofing				51.15	895.21	511.55	1,406.75		-
11.00.41.10	demolition tiles									
11,00,41,10	demolition floor tiles	108.23 m2	0.60	3.00	64.94	1,136.36	324.68	1,461.04	275 92	
	total: demolition tiles	100.23 1112	0.60	3.00	84.94	1,136.36	324.68	1,461.04	N. A. 45	
					01.04	1,100.00	OZ-NOO	17101104		
	TOTAL: CLEANING AND DEMOLITION				241.69	4,229.57	2,524.22	6,753.79		
17	TERRAIN INVENTORY									
17.00.90.10	terrain miscellaneous									
	repai terrain wali and gates	1.00 pc	0.00	750.00	0.00	0.00	750.00	750.00	15 17 17 1	
•	total: terrain miscellaneous				0.00	0.00	750.00	750.00		
	TOTAL: TERRAIN INVENTORY				0.00	0.00	750.00	750.00		
	I A 15.mi persidanta H24 mia 1 A 100				0.00	0.00	130.00	7 30.00		

Cdb 2017.08.06

code	description	amountunit	mh/unit	mat/unit s	nanhours	manhours \$	material \$	subtotal \$	pre unit	remarks
21	CONCRETE WORK									-
21.90.22.10	roof floor free span 0.15 (thickness)	46.80 m2	roof floor							
	formwork edges	1.76 m2	1.00	10.00	1.76	30.71	17.55	48.26	, 133 tm	
	formwork bottom	46.80 m2	1.00	10.00	46.80	819.00	468.00	1,287.00	7767 ·	
	remove formwork edges	1.76 m2	0.05	0.00	0.09	1.54	0.00	1.54	10 - 7	
	remove formwork bottom	46.80 m2	0.05	0.00	2.34	40.95	0.00	40.95	gi my - y	
	bottom 3/8"-#200	262.08 kg	0.08	1.60	20.97	366.91	419.33	786.24	Aire &	
	top 3/8"-#200	262.08 kg	0.08	1.60	20.97	366.91	419.33	786.24	· 105 - 41	
	chairs 3/8" 1.00 pc/m2 length= 1.20 m1	31.45 kg	0.08	1.60	2.52	44.03	50.32	94.35	e, ,	
	reinforcing loss 5%	27.78 kg		1.60	0.00	0.00	44.45	44.45	يُه تران	
	concrete PSI 3500 + pump	7.02 m3	3.00	225.79	21.06	368.55	1,585.05	1,953.60		
	concrete loss 5%	0.40 m3		225.79	0.00	0.00	90.54	90.54	2.73	
	anchoring in ringbeam	1.00 pc	8.00	250.00	8.00	140.00	250.00	390.00	٠, ,	
	paintwork concrete edges	1.76 m2	will be totali	zed at "46 PA	INT WORK	ı	-		2007	
	paintwork concrete bottom	46.80 m2	will be totall	zed at "46 PA	UNT WORK	1			162	
	total: roof floor free span 0.15 (thickness)	69.28 kg/m	3		124,49	2,178.60	3,344.56	5,523.16	'1º 02 m2	
1.91.31.10	roof edge 0.15x0.20 (wxh)	0.00 m1	roof level							
	formwork edges	0.00 m2	1.00	10.00	0.00	0.00	0.00	0.00		
	stirrups	0.00 kg	0.08	1.60	0.00	0.00	0.00	0.00		
	top	0.00 kg	0.08	1.60	0.00	0.00	0.00	0.00		
	remove formwork edges	0.00 m2	0.05	0.00	0.00	0.00	0.00	0.00		
	reinforcing loss 5%	0.00 kg	0.00	1.60	0.00	0.00	0.00	0.00		
	concrete PSI 3500 + pump	0.00 m3	3.00	225.79	0.00	0.00	0.00	0.00		
	concrete loss 5%	0.00 m3		225.79	0.00	0.00	0.00	0.00		
	fine plaster	0.00 m2	will be totali	zed at "40 PL		_	0.00	0.00		
	paintwork concrete edges	0.00 m2		zed at "46 PA						
	total: roof edge 0.15x0.20 (wxh)	3.55 12	11 00 10		0.00	0.00	0.00	0.00		
	TOTAL: CONCRETE WORK				124.49	2,178.60	3,344.56	5,523.16		
14	ROUGH CARPENTRY									
4.00.10.10	beams			c	olumns por	ch				
	6"x6"	15.40 m1	0.50	16.02	7.70	134.75	246.71	381.48	•• (
	fasteners	6.00 pc	0.00	50.00	0.00	0.00	300.00	300.00	•	
	moddeling columns	15.40 m1	2.00	5.00	30.80	539.00	77.00	616.00		
	total: beams				38.50	673.75	623.71	1,297.46		
4.91.12.10	wooden roof 79.92x1.00 (m2 x angle cort.)	79.92 m2	roof level	n	nain roof					
	fascia 2"x10"	14.40 m1	0.50	15.00	7.20	128.00	216.00	342.00	۱۱ "	
	battens 2*x4*	131.02 m1	0.30	7.00	39.30	687.84	917.11	1,604.95	·	
	fasteners wood work fasteners	79.92 m2	0.00	5.00	0.00	0.00	399.60	399.60		

Frontstreet 113 Apon monument

code	description	<u>a</u> mount unit	mh/unit	mat/unit n	nanhours	manhours \$	material \$	subtotal \$	prior un t	remarks
24.91.12.11		22.39 m2	roof level							
	fascia 2"x10"	14.25 m1	0.50	15.00	7.13	124.69	213.75	338.44	~ . 74, m	
	battens 2"x4"	36.70 m1	0.30	7.00	11.01	192.70	258.93	449.63	1, 1	
	gingerbread	9.25 m1	0.50	75,00	4.63	80.94	693.75	774.69	* *	
	fasteners wood work fasteners	22.39 m2	0.00	5.00	0.00	0.00	111.95	111.95		
	total: wooden roof 22.39x1.00 (m2 x angle corr.)				22.76	398.32	1,276.38	1,674.70	71 EC 4112	
	TOTAL: ROUGH CARPENTRY				107.77	1,685.91	3,432.81	5,318.72		
30	DOORS AND WINDOWS		v	vooden wind	ow frames					
30.00.10.10	Interior wooden frame and door	6.00 pc	general							
	frame meranti 67x114	6.00 pc	2.00	100.00	12.00	210.00	600.00	810.00	4. 10 0	
	door solid	6.00 pc	2.00	250.00	12.00	210.00	1,500.00	1,710.00	:- *	
	set hinges 3.5" Stanley	6.00 pc	0.30	7.50	1.80	31.50	45.00	76.50	507 .	
	passage lock	6.00 pc	0.30	15.00	1.80	31.50	90.00	121.50		
	door stopper	6.00 pc	0.10	5.00	0.60	10.50	30.00	40.50	71,	
	paintwork wooden frame and door	6.00 pc	0.00	100.00	0.00	0.00	600.00	600.00		
	total: Interior wooden frame and door	•			28.20	493.50	2,865.00	3,358.50		
30.00.12.10	exterior wooden frame and door	1.00 pc	general							
	frame meranti 67x114	0.25 pc	4.00	150.00	1.00	17.50	37.50	55.00	: ()	
	hard wood door	1.00 pc	8.00	500.00	8.00	140.00	500.00	640.00	1100	
	well	1.00 pc	1.00	100.00	1.00	17.50	100.00	117.50	1 1 2	
	glass openings	1.00 pc	0.00	400.00	0.00	0.00	400.00	400.00	107174	
	set hinges 3.5" Stanley	2.00 pc	0.30	7.50	0.60	10.50	15.00	25.50	11.70	
	key passage lock	1.00 pc	0.30	30.00	0.30	5.25	30.00	35.25	5 4 m	
	dead bolt	1.00 pc	0.30	19.06	0.30	5.25	19.06	24.31	ærsi pr	
	door open holder Buva	1.00 pc	0.50	49.00	0.50	8.75	49.00	57,75	51 th 10	
	paintwork wooden frame and door	1.00 pc	0.00	100.00	0.00	0.00	100.00	100.00	tāi es no	
	total: exterior wooden frame and door				11.70	204.75	1,250.56	1,455.31	1,475.31 /pc	
30.00.20.10	frames, windows and doors aluminum									
	RS louvre window 0.75x1.30, screens, particulier	6.00 pc	2.00	1,145.57	12.00	210.00	6,873.42	7,083.42	tending pr	
	RS louvre window 1.40x1.40, screens, particulier	1.00 pc	2.00	2,358.53	2.00	35.00	2,358.53	2,393.53	· /	bedroom left
	RS louvre window 1.80x1.40, no screens, particulier	1.00 pc	2.00	2,132.66	2.00	35.00	2,132.66	2,167.66	*1" "1, 1g.n	bedroom right
	total: frames, windows and doors aluminum	·			16.00	280.00	11,364.60	11,644.60		•
30.00.80.10	wooden shutters									
	wooden shutters	6.00 pc	12.00	750.00	72.00	1,260.00	4,500.00	5,760.00	19 12 1	
	total: wooden shutters	•			72.00	1,260.00	4,500.00	5,760.00		

code	description	amountunit	mh/unit	mat/unit	manhours	manhours \$	material \$	subtotal \$	<u> </u>	remarks
30.00.90.10	doors & windows miscellaneous							•		
	wooden window frames	6.00 pc	4.00	150.00	24.00	420.00	900.00	1,320.00		
	steel grills	1.00 pc	8.00	2,000.00	8.00	140.00	2,000.00	2,140.00	•	
	price increase after Irma	0.10 pc	0.00	11,364.60	0.00	0.00	1,136.46	1,136.46		
	total: doors & windows miscellaneous				32.00	560.00	4,035,45	4,596.46		
	TOTAL: DOORS AND WINDOWS				159.90	2,798.25	24,016.61	26,814.86		
32	STEPS, BALUSTRADES AND RAILINGS									
32.00.32.10	railings wood									
	rallings wood	11.60 m1	2.00	350.00	23.20	406.00	4,060.00	4,466.00		porch
	total: railings wood				23.20	406,00	4,060.00	4,465.00		
	TOTAL: STEPS, BALUSTRADES AND RAILINGS			,	23.20	406.00	4,060.00	4,466.00		
33	ROOFING									
33.00.10.10	concrete roof finish									
	sloping layer	46.80 m2	0.50	30.00	23.40	409.50	1,404.00	1,813.50		
	Liquid Rubber	46.80 m2	0.60	29.00	28.08	491.40	1,357.20	1,848.60		
	total: concrete roof finish				51.48	900.90	2,761.20	3,662.10		
33.91.10.10	metal roof sheets	79.92 m2	roof level	,	nain roof					
	felt paper	79.92 m2	0.10	1.65	7.99	139.86	131.87	271.73		
	steel roof sheets	79.92 m2	1.60	32.00	127.87	2,237.76	2,557.44	4,795.20		
	fasteners roof sheets	959.04 pc	0.05	1.00	47.95	839.16	959.04	1,798.20		
	flashing ridge cap	1.90 m1	0.60	35.00	1.14	19.95	68.50	88.45		
	flashing hip cap	29.95 m1	0.60	35.00	17.97	314.50	1,048.32	1,362.82		
	flashing gutter	32.90 m1	0.30	35.00	9.87	172.73	1,151.50	1,324.23		
	total: metal roof sheets				212.80	3,723.95	5,914.67	9,638.62	***	
33.91.10.11	metal roof sheets	22.39 m2	roof level		oorch roof					
	felt paper	22.39 m2	0.10	1.65	2.24	39.18	36.94	76.12		
	steel roof sheets	22.39 m2	1.60	32.00	35.82	626.91	716.47	1,343.38		
	fasteners roof sheets	268.68 pc	0.05	1.00	13.43	235.09	268.68	503.77		
	flashing hip cap	0.00 m1	0.60	35.00	0.00	0.00	0.00	0.00		
	flashing valley	0.00 m1	0.60	35.00	0.00	0.00	0.00	0.00		
	flashing gutter	9.25 m1	0.30	35.00	2.78	48.56	323.75	372.31		
	flashing end wall	5.00 m1	0.60	15.00	3.00	52.50	75.00	127.50		
	total: metal roof sheets		2.30		57.27	1,002.24	1,420.84	2,423.08	*	
	TOTAL: ROOFING				321.55	5,627.10	10,098.70	15,723.80		

Frontstreet 113 Apon monument

	description	amount unit	mh/unit	mat/unit r	nanhours	manhours \$	material \$	subtotal \$	ו שמריינים	remarks
41	TILE WORK									
41.00.11.10	floor tile work	108.23 m2	generai							
	screed	5.41 m3	6.00	145.00	32,47	568.18	784.63	1,352,81	710 00.	
	grout	108.23 m2	0.00	0.75	0.00	0.00	81.17	81.17		
	base tiles	54.11 m1	0.30	5.00	16.23	284.09	270.56	554.65	16.5 44	
	floor tile work labour	108.23 m2	1.00	0.00	108.23	1,893.94	0.00	1.893.94	1, 1, 1, 1, 1, 1	
	floor tile work material	111.47 m2	0.00	35.00	0.00	0.00	3,901.51	3,901.51	:	
	total: floor tile work			33.33	156.93	2,746.21	5,037.87	7,784.08	11 93 .m2	
	TOTAL: TILE WORK				156.93	2,746.21	5,037.87	7,784.08		
и	CEILING AND WALL SYSTEMS									
4.00.10.10	• • • • • • • • • • • • • • • • • • • •									
	sheetrock ceiling	66.60 m2	0.00	36.60	0.00	0.00	2,437.38	2,437.38	31 600	main interior
	total: system celling				0.00	0.00	2,437.38	2,437.38		
	TOTAL: CEILING AND WALL SYSTEMS				0.00	0.00	2,437.38	2,437.38		
16	PAINTWORK									
6.00.10.10	paintwork surface wood									
	wooden column	13.20 m1	0.20	2.00	2.64	46.20	26.40	72.60	· (11°	
	wooden decking	20.81 m2	0.30	6.00	6.24	109.27	124.88	234.14	11 55 1-7	ceiling porch
	fascia	28.65 m1	0.20	3.00	5.73	100.28	85.95	186.23	6.50,00	
	wooden railings	13.20 m1	0.30	3.00	3.96	69.30	39.60	108.90	6 .7	
	total: paintwork surface wood				18.57	325.04	276.83	601.87		
6.00.20.10	paintwork surface plaster/concrete									
	paintwork plaster	128.36 m2	0.50	6.00	64.18	1,123.11	770.13	1,893.24	1 % ,-	exterior
	paintwork plaster	190.90 m2	0.50	6.00	95.45	1,670.40	1,145.42	2,815.82	in a large	Interior
	paintwork concrete	48.56 m2	0.50	6.00	24.28	424.86	291.33	716.19	40 70 142	
	sheetrock	0.00 m2	0.50	4.00	0.00	0.00	0.00	0.00		
	total: paintwork surface plaster/concrete				183.91	3,218.36	2,206.88	5,425.24		
	TOTAL: PAINTWORK									

code	description	amountunit	mh/unit	mat/unit ma	nhours	manhours \$	material \$	subtotal \$	pro dat	remarks	1
50	GUTTERS AND DOWNSPOUTS										_
50.00.10.10	gutters gutters total: gutters	23.65 m1	0.50	15.00	11.83 11.83	208.94 206.94	354.75 354.76	581.69 561.69			
50.00.30.10	PVC downspouts 3" PVC spout pipes total: PVC downspouts	18.00 m1	0,50	18.00	9.00 9.00	157.50 157.50	324.00 324.00	481.50 481.5 0	<u> 2</u> 4, 75		
	TOTAL: GUTTERS AND DOWNSPOUTS				20.83	364.44	678.75	1,043.19			
53 53.00.90.10	SANITARY INSTALLATIONS sanitary miscellaneous plumbing update total: sanitary miscellaneous TOTAL: SANITARY INSTALLATIONS	1.00 pc	0.00	3,000.00	0.00 0.00	0.00 0.00 0.00	3,000.00 3,000.00 3,000.00	3,000.00 3,000.00 3,000.00	· 'n,		
70 70.00.92.10	electrical miscellaneous electrical update total: electrical miscellaneous TOTAL: ELECTRICAL INSTALLATIONS	1.00 pc	0.00	7,500.00	0.00	0.00 0.00	7,500.00 7,500.00 7,500.00	7,500.00 7,500.00 7,500.00	****		

Frontstreet 113 Apon monument

code	description	amount unit	mh/unit	mat/unit manhours	manhours \$	material \$	subtotal \$ prezion	remarks
-	TOTAL direct cost:		·	1,358.83	03 770 49	69,362.62	93,142.10 USD	
end	O (AL direct cost:			1,350.03	23,779.48	09,302.02	93,142.10 03D	
	Site cost	8.00%	over				7,451.37	
	subtotal_1						100,593.46 USD	
	Overhead	8.00%	over			_	8,047.48	
	subtotal_2					-	108,640.94 USD	
	Profit + Risk	8.00%	over			_	8,691.28	
	subtotal_3					_	117,332.22 USD	
	CAR Insurance	1.50%	over			_	1,759.98	
	subtotal_4						119,092.20 USD	
	unforeseeh	10.00%					11,909.22	
	subtotal_4						131,001.42 USD	
	turn-over tax	5.26%					6,890.67	
	TOTAL including unforeseen:						137,892.09 USD	•
	; · · ad							
	1 es is use	• •						